

2/29 BEST AVAILABLE COPY

Figure 2(a) (Prior Art)






Figure 2(b) (Prior Art)




3/29

BEST AVAILABLE COPY


Figure 3




4/29 BEST AVAILABLE COPY



5/29 BEST AVAILABLE COPY




Replacement Sheet BEST AVAILABLE COPY




BEST AVAILABLE COPY





8/29 DEST AVAILABLE COPY



10/29 BEST AVAILABLE COPY

Figure 9(a)




Figure 9(b)





Figure 9(c)



11/29

BEST AVAILABLE COPY

Figure 9(d)





Figure 9(e)



12/29

BEST AVAILABLE COPY

Figure 10(a)







Figure 10(b)




13/29 BEST AVAILABLE COPY



BEST AVAILABLE COPY




15/29 BEST AVAILABLE COPY




16/29 BEST AVAILABLE COPY

Figure 14




BEST AVAILABLE COPY

Figure 15




18/29 BEST AVAILABLE COPY

Figure 16




Replacement Sheet BEST AVAILABLE COPY 19/29

Figure 17(a)





20/29 BEST AVAILABLE COPY

Figure 17(b)



Replacement Sheet BEST AVAILABLE COPY






22/29

BEST AVAILABLE COPY

Figure 18(c)



BEST AVAILABLE COPY

23/29





Figure 18(e)



BEST AVAILABLE COPY

24/29


Figure 19

Line Pair Assembly <u>504</u> Cassette 414 Subassembly 416 Fiber Way 506 Line Assembly **FBG** 500 Assembly 404 **PCBs** 406 Fiber Way **FBG** 506 Assembly 404 Assembly 410 Line

Assembly 501


DEST AVAILABLE COPY

Figure 20




BEST AVAILABLE COPY

Figure 21



BEST AVAILABLE COPY


Figure 22



28/29

BEST AVAILABLE COPY

Figure 23



29/29

BEST AVAILABLE COPY

Figure 24

